



On the BMA drawings the distance between the steels is 1509mm is there an issue on fixing of the panels .