

SAFETY PROTECTION SHEET

Roth Compact Flex Fix



Signal word:

Danger

Hazard statements:

H318 Causes serious eye damage.

H315 Causes skin irritation.

H335 May cause respiratory irritation.

General

Article no.

S796, S7960

Use of the substance / preparation

Cement-based flexible adhesive that ensures full adhesive covering and a high adhesive capacity on pressure-resistant EPS and aluminium in connection with laying of tiles on the Roth Compact system or the Roth Clima Comfort system.

PC1 Adhesives, Sealants

PC9 Coatings and Paints, Fillers, Putties, Thinners

PC10 Building and construction substances not covered elsewhere

PROC5 Mixing or blending in batch processes for formulation of preparations and articles (multistage and/or significant contact)

PROC8b Transfer of substance or preparation (charging/discharging) from/to vessels/large containers at dedicated facilities

PROC9 Transfer of substance or preparation into small containers (dedicated filling line, including weighing)

First aid procedures

General

Remove affected person from source of contamination. Contaminated clothing should be removed immediately. Get medical attention if any discomfort continues.

Inhalation

Fresh air. Ensure free airways, seek medical attention if irritation persists.

Skin contact

Remove contaminated clothing. Wash the skin immediately with soap and water.

Eye contact

Important! Immediately rinse with water for at least 15 minutes. Make sure to remove any contact lenses from the eyes before rinsing. Immediately transport to hospital or eye specialist. Continue flushing during transport to hospital.

Ingestion

When small amounts (a mouthful or less): Rinse mouth with water. Drink water or milk. Contact your doctor for evaluation.

For larger quantities than described above: Rinse mouth with water. Drink water or milk. Seek immediate medical attention.

Acute symptoms and effects

Irritating to eyes and skin

Other information

When in doubt, or when symptoms persist - seek medical help. General health check.

Protective equipment

Symbols



Suitable eye protection

Wear approved chemical safety goggles where eye exposure is reasonably probable.

Skin- / hand protection, long term contact

< 8 h Neoprene, nitrile, polyethylene or PVC.

Skin- / hand protection, long term contact

> 8 h Neoprene, nitrile, polyethylene or PVC.

Suitable materials

Neoprene, nitrile, polyethylene or PVC.

Recommended type of equipment

Wear a dust mask class P2 for work in dusty areas.

Recommended respiratory protection

Dust filter P2 (for fine dust), EN 143

Fire fighting measures

Suitable extinguishing media

Choose in relation to the surrounding fire.

Improper extinguishing media

None.

Fire and explosion hazards

Not relevant.

Fire fighting procedures

Use extinguishing measures appropriate to local circumstances and the surrounding environment.

Personal protective equipment

No recommendation given.

Other information

Fight fire with normal precautions from a reasonable distance.

Preventive Measures to contain emissions

General measures

Use personal protective equipment as specified in section 8.

Personal protection measures

Use specified protective equipment. Avoid inhalation of dust. Avoid contact with skin and eyes. Use recovery methods without development of dust.

Environmental precautionary measures

Collect and dispose of spillage as indicated in section 13.

Containment

No recommendation given.

Other instructions

See section 1 for emergency contact information.

See section 8 for information on appropriate personal equipment.

See section 13 for waste disposal.

Responsible company**Company name**

Roth North Europe A/S

Postal address

DK-3600

Postcode

3600-Frederikssund

Country

Denmark

Telephone number

+45 47380121